

**KENTUCKY HISTORIC PROPERTIES SURVEY FORM
2016-1**

COUNTY Taylor
RESOURCE # TAC-381
EVALUATION S/ Ineligible

SHPO EVALUATION

Choose One

CONDITION

G / Good - In good state of repair

For SHPO Use Only

1. **NAME OF RESOURCE:** E-911 Call Center
HOW DETERMINED:
4/ Original or later significant uses of property
2. **ADDRESS/LOCATION:** 125 W. First Street
Campbellsville, KY 42718
OWNER CONTACT (if known): CityofC'ville
110 S. Columbia Ave., Campbellsville, KY
3. **GEOGRAPHIC DATA:**
Quad: Campbellsville **Date:** 1987
Lat: 37.340660 **Long:** -85.346547
4. **FIELD RECORDER/AFFILIATION:** Donna
Logsdon
Architect
5. **DATE RECORDED:** 10/20/17
6. **SPONSOR/INITIATION:**
2 / Certified Local Govt project
Sponsor Name: City of Campbellsville &
Kentucky Heritage Council
7. **PREVIOUSLY RECORDED:**
0/ Not Previously Recorded
8. **REPORT/NR REFERENCE:** Campbellsville CLG
Survey 2017-2018
9. **ORIGINAL PRIMARY FUNCTION:** 02B:
Professional office
10. **CURRENT PRIMARY FUNCTION:** 02B:
Professional office
11. **ORIGINAL CONSTRUCTION DATE:**
Estimated: 1/ 1975-2000 **Documented:** 1992
12. **MAJOR ADDITIONS/MODIFICATIONS (specify):**
Choose One Choose One
13. **MODIFICATION ASSESSMENT:**
Choose One
14. **CONSTRUCTION METHOD AND MATERIAL:**
Original/Primary (if known): P1/ Concrete block
Subsequent/Secondary (if known): Choose One
Other:
15. **EXTERIOR WALL CLADDING:**
Original (if known): C/ Brick veneer
Current: Choose One
16. **DIMENSIONS:**
Height: A/ 1 story **Acreage:**

26. PHOTO A



17. **ARCHITECTURAL FORM/SHAPE:** A/ Square or rectangular
18. **ARCHITECTURAL TYPE (choose from applicable list(s)):**
Early 19th-Mid 19th century types Choose One
Mid-to-Late 19th century types Choose One
Late 19th-Mid 20th century types Choose One
Other U/ Undetermined/not applicable

19. **ARCHITECTURAL STYLE (choose from applicable list(s)):**
Early Republic c. 1780-1835 Choose One
Mid-19th Century/Romantic c. 1835-1880 Choose One
Victorian c. 1840-1910 Choose One
Turn-of-Century Revival Styles c. 1880-1940 Choose One
20th Century American c. 1900-1940 Choose One
Modern c. 1920-Present Y/ Contemporary
Other O/ Other (specify) No Style

20. FOUNDATION WALLS:

Type: 2 / Continuous

Material: R / Poured Concrete

21. ROOFING:

Configuration: B/ Gable, front

Slope: 2/ Normal - Between 30 and 45 degrees **Roof**

Covering: 5/ Asphalt shingle

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: Original Replacement

Current Material: V/ Vinyl

Sash Operation: D/ Double or Single Hung

Glazing Pattern: S/ Single Light

24. NUMBER OF SUPPORT RESOURCES: 0/ None
(If yes, complete #27 and #28 below.)

25. COMMENTS/HISTORICAL INFORMATION (Complete on
Continuation Sheet)

PHOTO B (Place Additional Photos below under 26.
continued)



SHPO Review Date _____

SHPO Data Entry Date _____

COUNTY: Taylor

RESOURCE NUMBER: TAC-381

27. SUPPORT RESOURCES:

SITE PLAN KEY	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):



COUNTY: Taylor

RESOURCE NUMBER: TAC-381

29. MAP (Scan or attach copy of map showing exact location of resources):




25. (continued) COMMENTS/HISTORICAL INFORMATION:

This one-story brick building was constructed on this site in 1998. A house was originally on this site but was moved or torn down to this E-911 Call Center. It has 1,800 SF.


COUNTY: Taylor

RESOURCE NUMBER: TAC-377

26. (continued) ADDITIONAL IMAGES:



Caption:



Caption: