

**KENTUCKY HISTORIC PROPERTIES SURVEY FORM
2016-1**

COUNTY Taylor
RESOURCE # TAC-391
EVALUATION S/ Ineligible

SHPO EVALUATION

Choose One

CONDITION

G / Good - In good state of repair

For SHPO Use Only

- 1. **NAME OF RESOURCE:** Discount Used Cars
HOW DETERMINED:
4/ Original or later significant uses of property
- 2. **ADDRESS/LOCATION:** 200 Lebanon Avenue
Campbellsville, KY 42718
OWNER CONTACT (if known): Lebanon Ave.
102 Diane Dr., Campbellsville, KY 42719
- 3. **GEOGRAPHIC DATA:**
Quad: Campbellsville **Date:** 1987
Lat: 37.342156 **Long:** -85.341592
- 4. **FIELD RECORDER/AFFILIATION:** Donna
Logsdon
Architect
- 5. **DATE RECORDED:** 10/20/17
- 6. **SPONSOR/INITIATION:**
2 / Certified Local Govt project
Sponsor Name: City of Campbellsville &
Kentucky Heritage Council
- 7. **PREVIOUSLY RECORDED:**
0/ Not Previously Recorded
- 8. **REPORT/NR REFERENCE:** Campbellsville CLG
Survey 2017-2018

- 9. **ORIGINAL PRIMARY FUNCTION:** 02E:
Specialty store/shop
- 10. **CURRENT PRIMARY FUNCTION:** 02E:
Specialty store/shop
- 11. **ORIGINAL CONSTRUCTION DATE:**
Estimated: 1/ 1975-2000 **Documented:** 1980s
- 12. **MAJOR ADDITIONS/MODIFICATIONS (specify):**
Choose One Choose One
- 13. **MODIFICATION ASSESSMENT:**
Choose One
- 14. **CONSTRUCTION METHOD AND MATERIAL:**
Original/Primary (if known): P1/ Concrete block
Subsequent/Secondary (if known): Choose One
Other:
- 15. **EXTERIOR WALL CLADDING:**
Original (if known): Z/ Wood vertical board

Current:

- 16. **DIMENSIONS:**
Height: A/ 1 story **Acreage:**

26. PHOTO A



- 17. **ARCHITECTURAL FORM/SHAPE:** A/ Square or rectangular
- 18. **ARCHITECTURAL TYPE (choose from applicable list(s)):**
Early 19th-Mid 19th century types Choose One
Mid-to-Late 19th century types Choose One
Late 19th-Mid 20th century types Choose One
Other U/ Undetermined/not applicable
- 19. **ARCHITECTURAL STYLE (choose from applicable list(s)):**
Early Republic c. 1780-1835 Choose One
Mid-19th Century/Romantic c. 1835-1880 Choose One
Victorian c. 1840-1910 Choose One
Turn-of-Century Revival Styles c. 1880-1940 Choose One
20th Century American c. 1900-1940 Choose One
Modern c. 1920-Present Y/ Contemporary
Other O/ Other (specify) No Style

- 20. **FOUNDATION WALLS:**
Type: 2 / Continuous
Material: R / Poured Concrete

- 21. **ROOFING:**
Configuration: I/ Hip
Slope: 1/ Low- Less than 30 degrees **Roof Covering:**
9/ Metal sheet roofing (not standing seam)
- 22. **ARCHITECT/BUILDER (if known):**

- 23. **WINDOWS:** Original Replacement
Current Material: M/ Metal
Sash Operation: F/ Fixed
Glazing Pattern: S/ Single Light

- 24. **NUMBER OF SUPPORT RESOURCES:** 0/ None
(If yes, complete #27 and #28 below.)

- 25. **COMMENTS/HISTORICAL INFORMATION** (Complete on
Continuation Sheet)

PHOTO B (Place Additional Photos below under 26.
continued)



SHPO Review Date _____

SHPO Data Entry Date _____


COUNTY: Taylor

RESOURCE NUMBER: TAC-391

27. SUPPORT RESOURCES:

SITE PLAN KEY	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):



COUNTY: Taylor

RESOURCE NUMBER: TAC-391

29. MAP (Scan or attach copy of map showing exact location of resources):



25. (continued) COMMENTS/HISTORICAL INFORMATION:

This one-story building is the office for the surrounding car lot. It has 1,135 SF.


COUNTY: Taylor

RESOURCE NUMBER: TAC-391

26. (continued) ADDITIONAL IMAGES:



Caption: TAC389_03 The building on the left is the Kessler Realty and Auction Company office. The front façade faces north.



Caption: