## KENTUCKY HISTORIC PROPERTIES SURVEY FORM 2016-1

COUNTY Taylor
RESOURCE # TAC-411
EVALUATION N/ Eligible Member of a Group

SHPO EVALUATION
Choose One
CONDITION

G / Good - In good state of repa

For SHPO Use Only

1. NAME OF RESOURCE: Lynn Wholesale Electric HOW DETERMINED:

4/ Original or later signficant uses of property

2. ADDRESS/LOCATION: 334 W. Main St.

Campbellsville, KY 42718

**OWNER CONTACT (if known):** Pogue & Rogers 334 E. Main St., Campbellsville, KY 42718

3. GEOGRAPHIC DATA:

Quad: Campbellsville Date: 1987 Lat: 37.342073 Long: -85.341256 4. FIELD RECORDER/AFFILIATION: Donna

Logsdon Architect

**5. DATE RECORDED:** 10/20/17

6. SPONSOR/INITIATION:

2 / Certified Local Govt project

Sponsor Name: City of Campbellsville &

Kentucky Heritage Council

PREVIOUSLY RECORDED:0/ Not Previously Recorded

8. REPORT/NR REFERENCE: Campbellsville CLG

Survey 2017-2018

9. ORIGINAL PRIMARY FUNCTION: 02E:

Specialty store/shop

**10. CURRENT PRIMARY FUNCTION:** 02E:

Specialty store/shop

11. ORIGINAL CONSTRUCTION DATE:

**Estimated:** 2/1950-1974 **Documented:** 1960s

12. MAJOR ADDITIONS/MODIFICATIONS (specify):

Choose One Choose One

13. MODIFICATION ASSESSMENT:

Choose One

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): P1/ Concrete block Subsequent/Secondary (if known): Choose One

Other:

15. EXTERIOR WALL CLADDING:

Original (if known): U/ Corrugated metal

Current: Choose One

16. DIMENSIONS:

Height: A/ 1 story Acreage:

**26. PHOTO A** 



17. ARCHITECTURAL FORM/SHAPE: A/ Square or rectangular

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Early 19<sup>th</sup>-Mid 19<sup>th</sup> century types Choose One Mid-to-Late 19<sup>th</sup> century types Choose One Late 19<sup>th</sup>-Mid 20<sup>th</sup> century types Choose One Other U/ Undetermined/not applicable

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Early Republic c. 1780-1835 Choose One

Mid-19th Century/Romantic c. 1835-1880 Choose One

Victorian c. 1840-1910 Choose One

Turn-of-Century Revival Styles c. 1880-1940 Choose One

20th Century American c. 1900-1940 Choose One

Modern c. 1920-Present Choose One Other O/ Other (specify) No Style

20. FOUNDATION WALLS:

Type: 2 / Continuous

Material: R / Poured Concrete

21. ROOFING:

Configuration: B/ Gable, front

Slope: 1/ Low-Less than 30 degrees Roof Covering:

9/ Metal sheet roofing (not standing seam)

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: Original Replacement

Current Material: M/ Metal Sash Operation: F/ Fixed Glazing Pattern: S/ Single Light

**24. NUMBER OF SUPPORT RESOURCES:** 0/ None

(If yes, complete #27 and #28 below.)

25. COMMENTS/HISTORICAL INFORMATION (Complete on

Continuation Sheet)

**PHOTO B** (Place Additional Photos below under 26. continued)

SHPO Review Date \_\_\_\_\_ SHPO Data Entry Date \_\_\_\_

**COUNTY:** Taylor

**RESOURCE NUMBER:** TAC-411

## **27. SUPPORT RESOURCES:**

SITE PLAN KEY	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One

28.	. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers		

**COUNTY:** Taylor

**RESOURCE NUMBER:** TAC-411

## 29. MAP (Scan or attach copy of map showing exact location of resources):



## 25. (continued) COMMENTS/HISTORICAL INFORMATION:

This one-story building was built in the 1960s for Lynn Wholesale Electric which occupied the building for many years. Recently, it was renovated and is now occupied by Body Sculptors, a physical fitness business. It has 2,592 SF.

RES	SOURCE NUMBER: TAC-411	
26.	(continued) ADDITIONAL IMAGES:	
	Caption:	
	Caption:	

**COUNTY:** Taylor