

(KHC 2011-1)

RESOURCE # TAC-42

EVALUATION N / Eligible: member of a group

SHPO EVALUATION _____

DESTROYED _____

1. NAME OF RESOURCE (how determined):
4 / Original or later significant uses of the property
Commercial Building; Artesanias Angel Pottery

2. ADDRESS/LOCATION:
126 E. Main Street
Campbellsville, KY 42718

3. UTM REFERENCE:
Quad Name: Campbellsville Date: 1970 PR 1987
Zone: 16 Method: C / Commonwealth Base Map
Easting: 646652 Northing: 4133968

4. OWNER/ADDRESS:
Daniel & Martha Aguayo
1224 S. 59th Avenue
Cicero, IL 60804

5. FIELD RECORDER/AFFILIATION:
Donna Logsdon, Architect

6. DATE RECORDED: 9/7/2012

7. SPONSOR:
City of Campbellsville & Kentucky Heritage Council

8. INITIATION: 2 / CLG

9. OTHER DOCUMENTATION:
 Survey HABS/HAER NR
 KY Landmark

10. REPORT/NR REFERENCE:
Campbellsville Historic Commercial District

11. ORIGINAL PRIMARY FUNCTION:
02: Commercial - F: General store/department store

12. CURRENT PRIMARY FUNCTION:
960: Work in Progress

13. CONSTRUCTION DATE: Estimated 5: 1875-1899
Documented: 1886-1895 Historians

14. DATE OF MAJOR ADDITIONS/MODIFICATIONS (specify):
1: 1975-2000: 1997 enclosed storefront & transom
windows
A: 2001-Present 2008 replaced second floor
windows

15. CONSTRUCTION METHOD AND MATERIAL:
Original/Primary: B0 / Brick
Subsequent/Secondary: _____

16. DIMENSIONS: Height: C: 2 Story

Width: 3 Depth: 2 Acreage:

17. PLAN:
First: U / Undetermined/not applicable
Second: _____

18. STYLISTIC INFLUENCE:
First: 4:2: Italianate
Second: _____

19. FOUNDATION:
Type: 2 / Continuous
Material: B / Brick

20. PRIMARY WALL MATERIAL:
Original: E / Brick, common bond
Replacement: _____

21. ROOF CONFIGURATION AND COVERING:
Configuration: Q / Flat
Covering: 6 / Built-up (tar)

22. CONDITION:
F / Fair-under maintained

23. MODIFICATION: 2 / Moderate alteration

24. ARCHITECT/BUILDER:

25. PHOTOGRAPH FILE:
TAC42_01

26. WINDOWS: Original Replacement
Type: Vinyl

TAC42_01



COMMENTS/HISTORICAL INFORMATION:
See continuation sheet


27. SUPPORT RESOURCES:

SITE PLAN KEY	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #26 was answered or if you are using sub-numbers):



29. MAP (Scan or attach copy of map showing exact location of resources): TAC-42 Map CO9-18-15A



Commercial Building; D.W. Gowdy General Store (TAC-42)

By 1895, this two-story brick building housed the west half of the D.W. Gowdy General Store on the first floor. Gowdy owned the building from the late-1800s until the early 1900s. At one time, the second floor was occupied by Martin Spurling a local photographer and undertaker. The building was also occupied by a used and new furniture and appliance store, pool room, and the Firestone Store. (Historians)