

**KENTUCKY HISTORIC PROPERTIES SURVEY FORM
2016-1**

COUNTY Taylor

RESOURCE # TAC-420

EVALUATION N/ Eligible Member of a Group

SHPO EVALUATION

Choose One

CONDITION

G / Good - In good state of repair

For SHPO Use Only

1. NAME OF RESOURCE: Barbara's Styling Station
HOW DETERMINED: Choose One

2. ADDRESS/LOCATION: Hotchkiss Ave.
Campbellsville, KY 42718

OWNER CONTACT (if known): TaylorCoBank
POB 200, Campbellsville, KY 42719

3. GEOGRAPHIC DATA:

Quad: Campbellsville **Date:** 1987

Lat: 37.341516 **Long:** -85.340446

4. FIELD RECORDER/AFFILIATION: Donna
Logsdon
Architect

5. DATE RECORDED: 10/20/17

6. SPONSOR/INITIATION:

2 / Certified Local Govt project

Sponsor Name: City of Campbellsville &
Kentucky Heritage Council

7. PREVIOUSLY RECORDED:

0 / Not Previously Recorded

8. REPORT/NR REFERENCE: Campbellsville CLG
Survey 2017-2018

9. ORIGINAL PRIMARY FUNCTION: 02B:
Professional office

10. CURRENT PRIMARY FUNCTION: 99V:
Vacant abandoned (site extant, but not in
service)

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 2/ 1950-1974 **Documented:** 1960s

12. MAJOR ADDITIONS/MODIFICATIONS (specify):
Choose One Choose One

13. MODIFICATION ASSESSMENT:

Choose One

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): P1/ Concrete block

Subsequent/Secondary (if known): Choose One

Other:

15. EXTERIOR WALL CLADDING:

Original (if known): C/ Brick veneer

Current: Choose One

16. DIMENSIONS:

Height: A/ 1 story **Acreage:**

26. PHOTO A



17. ARCHITECTURAL FORM/SHAPE: A/ Square or rectangular

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Early 19th-Mid 19th century types Choose One

Mid-to-Late 19th century types Choose One

Late 19th-Mid 20th century types Choose One

Other U/ Undetermined/not applicable

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Early Republic c. 1780-1835 Choose One

Mid-19th Century/Romantic c. 1835-1880 Choose One

Victorian c. 1840-1910 Choose One

Turn-of-Century Revival Styles c. 1880-1940 Choose One

20th Century American c. 1900-1940 Choose One

Modern c. 1920-Present Choose One

Other O/ Other (specify) No Style

20. FOUNDATION WALLS:

Type: 2 / Continuous

Material: R / Poured Concrete

21. ROOFING:

Configuration: A/ Gable, side

Slope: 2/ Normal - Between 30 and 45 degrees **Roof**

Covering: 5/ Asphalt shingle

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: Original Replacement

Current Material: M/ Metal

Sash Operation: F/ Fixed


Glazing Pattern: S/ Single Light

24. NUMBER OF SUPPORT RESOURCES: 0/ None

(If yes, complete #27 and #28 below.)

25. COMMENTS/HISTORICAL INFORMATION (Complete on
Continuation Sheet)

PHOTO B (Place Additional Photos below under 26.
continued)



SHPO Review Date _____

SHPO Data Entry Date _____

COUNTY: Taylor

RESOURCE NUMBER: TAC-420

27. SUPPORT RESOURCES:

SITE PLAN KEY	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):



COUNTY: Taylor

RESOURCE NUMBER: TAC-420

29. MAP (Scan or attach copy of map showing exact location of resources):




25. (continued) COMMENTS/HISTORICAL INFORMATION:

This one-and-a half story building was constructed in the 1960s as part of an open air shopping center. It was occupied by Barbara's Styling Station. It is currently vacant. It has 1,188 SF.


COUNTY: Taylor

RESOURCE NUMBER: TAC-420

26. (continued) ADDITIONAL IMAGES:



Caption:



Caption: