

**KENTUCKY HISTORIC PROPERTIES SURVEY FORM
2016-1**

COUNTY Taylor

RESOURCE # TAC-422

EVALUATION N/ Eligible Member of a Group

SHPO EVALUATION

Choose One

CONDITION

G / Good - In good state of repair

For SHPO Use Only

1. **NAME OF RESOURCE:** Coppock's Applicances
HOW DETERMINED:
4/ Original or later significant uses of property
2. **ADDRESS/LOCATION:** 100 MLK Blvd..
Campbellsville, KY 42718
OWNER CONTACT (if known): TaylorCoBank
P.O. Box 200, Campbellsville, KY 42719
3. **GEOGRAPHIC DATA:**
Quad: Campbellsville **Date:** 1987
Lat: 37.341205 **Long:** -85.340570
4. **FIELD RECORDER/AFFILIATION:** Donna
Logsdon
Architect
5. **DATE RECORDED:** 10/20/17
6. **SPONSOR/INITIATION:**
2 / Certified Local Govt project
Sponsor Name: City of Campbellsville &
Kentucky Heritage Council
7. **PREVIOUSLY RECORDED:**
0/ Not Previously Recorded
8. **REPORT/NR REFERENCE:** Campbellsville CLG
Survey 2017-2018
9. **ORIGINAL PRIMARY FUNCTION:** 02H:
Warehouse/commercial storage
10. **CURRENT PRIMARY FUNCTION:** 02H:
Warehouse/commercial storage
11. **ORIGINAL CONSTRUCTION DATE:**
Estimated: 2/ 1950-1974 **Documented:** 1960s
12. **MAJOR ADDITIONS/MODIFICATIONS (specify):**
Choose One Choose One
13. **MODIFICATION ASSESSMENT:**
Choose One
14. **CONSTRUCTION METHOD AND MATERIAL:**
Original/Primary (if known): P1/ Concrete block
Subsequent/Secondary (if known): Choose One
Other:
15. **EXTERIOR WALL CLADDING:**
Original (if known): D/ Brick, other bond type

Current: Choose One

16. **DIMENSIONS:**
Height: A/ 1 story **Acreage:**

26. PHOTO A



17. **ARCHITECTURAL FORM/SHAPE:** A/ Square or rectangular
18. **ARCHITECTURAL TYPE (choose from applicable list(s)):**
Early 19th-Mid 19th century types Choose One
Mid-to-Late 19th century types Choose One
Late 19th-Mid 20th century types Choose One
Other U/ Undetermined/not applicable
19. **ARCHITECTURAL STYLE (choose from applicable list(s)):**
Early Republic c. 1780-1835 Choose One
Mid-19th Century/Romantic c. 1835-1880 Choose One
Victorian c. 1840-1910 Choose One
Turn-of-Century Revival Styles c. 1880-1940 Choose One
20th Century American c. 1900-1940 Choose One
Modern c. 1920-Present Choose One
Other O/ Other (specify) No Style

20. **FOUNDATION WALLS:**
Type: 2 / Continuous
Material: R / Poured Concrete

21. **ROOFING:**
Configuration: B/ Gable, front
Slope: 2/ Normal - Between 30 and 45 degrees **Roof**
Covering: 5/ Asphalt shingle
22. **ARCHITECT/BUILDER (if known):**

23. **WINDOWS:** Original Replacement
Current Material: X/ Other enclosed
Sash Operation: X/ Other unknown
Glazing Pattern: Choose One

24. **NUMBER OF SUPPORT RESOURCES:** 0/ None
(If yes, complete #27 and #28 below.)

25. **COMMENTS/HISTORICAL INFORMATION** (Complete on
Continuation Sheet)

PHOTO B (Place Additional Photos below under 26.
continued)



SHPO Review Date _____

SHPO Data Entry Date _____


COUNTY: Taylor

RESOURCE NUMBER: TAC-422

27. SUPPORT RESOURCES:

SITE PLAN KEY	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):



COUNTY: Taylor

RESOURCE NUMBER: TAC-422

29. MAP (Scan or attach copy of map showing exact location of resources):




25. (continued) COMMENTS/HISTORICAL INFORMATION:

This one-story building was constructed in the 1960s for Coppock's Appliances. It is currently vacant. It has 5,624 SF.


COUNTY: Taylor

RESOURCE NUMBER: TAC-422

26. (continued) ADDITIONAL IMAGES:



Caption:



Caption: