KENTUCKY HISTORIC PROPERTIES SURVEY FORM 2016-1

COUNTY Taylor **RESOURCE # TAC-434 EVALUATION** S/ Ineligible **SHPO EVALUATION**

Choose One

CONDITION

G / Good - In good state of repa

For SHPO Use Only

1. NAME OF RESOURCE: Rescue Squad **HOW DETERMINED:**

4/ Original or later signficant uses of property

2. ADDRESS/LOCATION: 105 S. Columbia Ave.

Campbellsville, KY 42718

OWNER CONTACT (if known): CityofC'ville 110 S. Columbia Ave., Cville, KY 42718

3. GEOGRAPHIC DATA:

Quad: Campbellsville **Date:** 1987 **Lat:** 37.339695 **Long:** -85.344969 4. FIELD RECORDER/AFFILIATION: Donna

Logsdon Architect

5. **DATE RECORDED:** 10/20/17

6. SPONSOR/INITIATION:

2 / Certified Local Govt project

Sponsor Name: City of Campbellsville &

Kentucky Heritage Council

7. PREVIOUSLY RECORDED: 0/ Not Previously Recorded

8. REPORT/NR REFERENCE: Campbellsville CLG

Survey 2017-2018

Material: C / Concrete Block

9. ORIGINAL PRIMARY FUNCTION: 04K:

Govt/Public Other

10. CURRENT PRIMARY FUNCTION: 04K:

Govt/Public Other

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 1/1975-2000 Documented: 1982 12. MAJOR ADDITIONS/MODIFICATIONS (specify): Choose One Choose One

13. MODIFICATION ASSESSMENT:

Choose One

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): P1/ Concrete block Subsequent/Secondary (if known): Choose One Other:

15. EXTERIOR WALL CLADDING:

Original (if known): V/ Aluminum siding

Current: Choose One

16. DIMENSIONS:

Height: A/ 1 story Acreage:

26. PHOTO A



17. ARCHITECTURAL FORM/SHAPE: A/ Square or rectangular

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Early 19th-Mid 19th century types Choose One Mid-to-Late 19th century types Choose One Late 19th-Mid 20th century types Choose One Other U/ Undetermined/not applicable

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Early Republic c. 1780-1835 Choose One

Mid-19th Century/Romantic c. 1835-1880 Choose One

Victorian c. 1840-1910 Choose One

Turn-of-Century Revival Styles c. 1880-1940 Choose One

20th Century American c. 1900-1940 Choose One

Modern c. 1920-Present Y/ Contemporary

Other O/ Other (specify) No Style

20. FOUNDATION WALLS:

Type: 2 / Continuous

21. ROOFING:

Configuration: B/ Gable, front

Slope: 1/ Low- Less than 30 degrees Roof Covering:

9/ Metal sheet roofing (not standing seam)

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: Original Replacement

Current Material: Choose One Sash Operation: Choose One Glazing Pattern: Choose One

24. NUMBER OF SUPPORT RESOURCES: 0/ None

(If yes, complete #27 and #28 below.)

25. COMMENTS/HISTORICAL INFORMATION (Complete on

Continuation Sheet)

PHOTO B (Place Additional Photos below under 26. continued)

SHPO Review Date	SHPO Data Entry Date
SHFO Review Date	SHPO Data Ellity Date

COUNTY: Taylor

RESOURCE NUMBER: TAC-434

27. SUPPORT RESOURCES:

SITE PLAN KEY	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL
		Choose One	Choose One
		Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One
	Choose One	Choose One	Choose One

28.	s. SITE PLAN (Complete if #24 was answered or if you are using sub-numb					

COUNTY: Taylor

RESOURCE NUMBER: TAC-434

29. MAP (Scan or attach copy of map showing exact location of resources):



25. (continued) COMMENTS/HISTORICAL INFORMATION:

This one-story brick building was constructed in 1982 as the Campbellsville Rescue Squad building. It has physical fitness and apparatus, offices, bunk beds, a kitchen and training rooms. It has 6,600 SF.

26.	(continued) ADDITIONAL IMA	GES:
	Caption:	
	Caption:	

RESOURCE NUMBER: TAC-434

COUNTY: Taylor